

<b>Project No.</b>	<b>Client</b>	<b>Location</b>	<b>Boring No.</b>	<b>Monitoring Well No.</b>	<b>Date</b>
00445	Beacon Bay Auto Wash	481 E. 17 <sup>th</sup> St., Costa Mesa	CB4		August 3, 2005
<b>PID</b>	<b>BLOWS/ft. Sampler</b>	<b>DEPTH in feet</b>	<b>USCS Designation &amp; Soil Type</b>	<b>Color</b>	<b>Secondary Characteristics</b>
0	6-6-7	<b>5</b>	Clayey Sands (SC)	Orange to Tan	Loose, Sl Moist, No Odor
0	11-15-17	<b>10</b>		Tan	M. Dense
0	13-18-22	<b>15</b>	Silty Sand (SM)	Brown	Dense, Moist
40	11-15-19	<b>20</b>	Clayey Sands (SC)	Olive Brown	M. Dense, Wet, Sl Odor
20	6-10-15	<b>25</b>		Brown	
0	9-12-15	<b>30</b>		Dark Grey	M. Dense, Wet, No Odor
10	8-10-12	<b>35</b>	Silty Clay (CL)		Stiff, Wet, Sl Odor
<b>Field Engineer</b>	<b>Drilling Contractor</b>	<b>Drilling Foreman</b>	Boring terminated at 35'. Groundwater encountered at 16-17'. Boring backfilled with soil from boring. Overflow soil drummed and manifested.		
M. Anselmo	J & H - Hollow Stem	Conrad			